



via Trieste, 10
31025 S. Lucia di Piave (TV)
Tel. +39 0438 6611
Fax +39 0438 661333
E-mail: walmec@walmec.com
Web: www.walmec.com



SERBATOIO HD

ISTRUZIONI PER L'USO

 **MAX** 1 Bar
15 Psi

Il serbatoio HD è un recipiente in pressione e si devono quindi osservare le seguenti precauzioni:

- prima di collegare l'aerografo all'aria compressa assicurarsi che il coperchio sia ben avvitato alla tazza e tutto il serbatoio sia ben avvitato all'aerografo.
- prima di aprire il coperchio scollegare l'aerografo dall'aria compressa.
- prima di svitare l'ugello scollegare l'aerografo dall'aria compressa.



WD40/06



via Trieste, 10
31025 S. Lucia di Piave (TV)
Tel. +39 0438 6611
Fax +39 0438 661333
E-mail: walmec@walmec.com
Web: www.walmec.com



HD GRAVITY CUP

HOW TO USE THE HD CUP

 **MAX** 1 Bar
15 Psi

The HD cup is an under pressure container.
The precautions as listed below must be followed very strictly:

- before connecting the spray gun to the compressed air hose, make sure to well screw on the lid of the cup and the cup to the spray gun.
- disconnect the spray gun from the compressed air hose before opening the cup lip.
- disconnect the compressed air hose before unscrewing the nozzle.



WD40/06